

A minerva jacket cast is used to immobilise the various levels of the cervical and thoracic spine. A minerva cast is generally made of fibreglass casting material and remains in place for approximately four to 12 weeks. The cast can only be removed by a cast technician or orthopaedic doctor.

From:

<https://neurosurgerywiki.com/wiki/> - **Neurosurgery Wiki**

Permanent link:

https://neurosurgerywiki.com/wiki/doku.php?id=minerva_jacket

Last update: **2024/06/07 02:52**

